

<input type="checkbox"/> IDTN <input checked="" type="checkbox"/> DTN	DATE 03/08/2018
CHANGE PREPARED BY Brad Anderson	JOB NO. 6805

## DRAWING TECHNICAL NOTICE

Delaware  
Resource Group

431 I Street East  
Bldg. 738  
Randolph AFB, TX 78150

DRAWING NO. 6805ABE200	SUFFIX	REV LTR <b>B</b>
DRAWING TITLE Computer Assembly, IOS Computer		SHEET <b>1</b> OF <b>8</b>

The parts specified in the contract for the IOS update were obsolete at the time of contract award.  
Sheet 1 of 2.

CHANGE CLASS		APPROVALS SEE TSSC TSCO NO.
I		<b>ECP 153</b>
II	X	

## WAS:

FN 1  
Part: 262-500002008-00; Nom: Chassis, PCI Bus, 15 Slot

FN 2  
Cage: Blank; Part: SN-208FB/BEDE; Material: Samsung


FN 3  
Part: ST310005N1A1AS-RK

FN 4  
Part: GTX 650TI


FN 7  
Part: GLC-00182; Nom: Windows 7 Ultimate, 64 Bit

FN 8  
Part: 4006; Nom: NFS Server for Windows

Drawing Sheet 3  
See image at right.



Drawing Sheet 4  
See image below



I/DTN NO. T0001

EFFECTIVITY  
6805ABE200 and all  
referencing drawings.

DISTRIBUTION STATEMENT D  
DISTRIBUTION AUTHORIZED TO THE DEPARTMENT OF DEFENSE AND U.S. DoD  
CONTRACTORS ONLY: (CRITICAL TECHNOLOGY), FEBRUARY 10, 2017. OTHER  
REQUESTS FOR THIS DOCUMENT SHALL BE REFERRED TO AGILE SUPPORT  
DIRECTORATE, SIMULATORS DIVISION (AFLCMC/WNS), WRIGHT-PATTERSON AIR  
FORCE BASE, OHIO 45433-7249

WARNING-This Document contains technical data whose export is restricted by the Arms  
Export Control Act (Title 22, U.S.C. Sec 2751, et seq.) or the Export Administration Act of 1979,  
Title 50, U.S.C., App. 2401, et seq.), as amended. Violations of these export laws are subject to  
severe criminal penalties. Disseminate in accordance with provision of DOD 5230.25.

DESTRUCTION NOTICE-For unclassified, limited documents destroy by any method that will  
prevent disclosure of contents or recognition of the document.

**PLANNING NOTE: NO CHANGE TO FORM,  
FIT OR FUNCTION – EXACT CHANGE OUT.**

See following sheet for “NOW”  
configuration.

<input type="checkbox"/> IDTN <input checked="" type="checkbox"/> DTN	DATE 03/08/2018
CHANGE PREPARED BY Brad Anderson	JOB NO. 6805

**DRAWING TECHNICAL NOTICE**

**Delaware**      431 I Street East  
**Resource Group**    Bldg. 738  
                                 Randolph AFB, TX 78150

DRAWING NO. 6805ABE200 (Continued)	SUFFIX	REV LTR <b>B</b>
DRAWING TITLE Computer Assembly, IOS Computer		SHEET <b>2</b> OF <b>8</b>

The parts specified in the contract for the IOS update were obsolete at the time of contract award. This is Sheet 2 of 2 of the DTN change documentation.	CHANGE CLASS	APPROVALS SEE TSSC TSCO NO.
	I	
	II	X
		<b>ECP 153</b>


**NOW:**

- FN 1  
Part: 262-500002310-00; Nom: Chassis, 4U, 15 Slot
- FN 2  
Cage: SL151; Part: GTCON; Material: LG Electronics
- FN 3  
Part: ST1000DM003
- FN 4  
Part: GTX 750TI

Drawing Sheet 4  
See image below


**/DTN NO. T0001**

EFFECTIVITY  
6805ABE200 and all  
referencing drawings.



- FN 7  
Part: 261500001097-00; Nom: Windows 10 Enterprise 2016, LTSC, 32 Bit
- FN 8  
Part: 4021; Part: NFS Server for Windows Ver 6.3.3


Drawing Sheet 3  
See image at right.



**PLANNING NOTE: NO CHANGE TO FORM,  
FIT OR FUNCTION – EXACT CHANGE OUT.**



PROPRIETARY MATERIAL  
Copyright © 2010. All rights reserved. FlightSafety International Inc.  
This document, including the information contained herein, is confidential and/or proprietary to FlightSafety International Inc. It shall not be reproduced, distributed, or disclosed to others, except as expressly authorized in writing.



FRONT VIEW

Fri 2015/01/23 8:42:27 AM Requested by: shead - Not for Production -

PROPRIETARY MATERIAL  
Copyright © 2010. All rights reserved. FlightSafety International Inc.  
This document, including the information contained herein, is confidential and/or proprietary to FlightSafety International Inc. It shall not be reproduced, distributed, or disclosed to others, except as expressly authorized in writing.

D

C

B


A

D

C

B

A



REAR VIEW

Fri 2015/01/23 8:42:27 AM Requested by: shead - Not for Production -

PROPRIETARY MATERIAL  
Copyright © 2010. All rights reserved. FlightSafety International Inc.  
This document, including the information contained herein, is confidential and/or proprietary to FlightSafety International Inc. It shall not be reproduced, distributed, or disclosed to others, except as expressly authorized in writing.


REAR →

← FRONT

TOP VIEW

Fri 2015/01/23 8:42:27 AM Requested by: shead - Not for Production -






PROPRIETARY MATERIAL  
Copyright © 2010. All rights reserved. FlightSafety International Inc.  
This document, including the information contained herein, is confidential and/or proprietary to FlightSafety International Inc. It shall not be reproduced, distributed, or disclosed to others, except as expressly authorized in writing.

CAUTION  
PART SUSCEPTIBLE TO DAMAGE BY  
ELECTROSTATIC DISCHARGE (ESD)

VIEW A-A  
SINGLE BOARD COMPUTER (SBC)  
CABLE ROUTING

Fri 2015/01/23 8:42:27 AM Requested by: shead - Not for Production -



PROPRIETARY MATERIAL  
Copyright © 2010. All rights reserved. FlightSafety International Inc.  
This document, including the information contained herein, is confidential and/or proprietary to FlightSafety International Inc. It shall not be reproduced, distributed, or disclosed to others, except as expressly authorized in writing.

Fri 2015/01/23 8:42:27 AM Requested by: shead - Not for Production -