

**SOFTWARE VERSION DESCRIPTION**  
**FOR VERSION 4.18N**  
**OF THE**  
**JOINT PRIMARY AIRCRAFT TRAINING SYSTEM**  
**GROUND BASED TRAINING SYSTEM**  
**T-6A FLIGHT TRAINING DEVICES**

**Contract #: FA8621-15-D-6258**  
**Task Order #: FA8617-17-F-6230**



Prepared by:  
Delaware Resource Group  
431 I Street East, RM 204  
Randolph AFB, TX 78150

Prepared for:  
Air Force Life Cycle Management Center  
Agile Combat Support Directorate  
Simulator Division  
Wright Patterson AFB, OH 45433-7249

**DISTRIBUTION STATEMENT "D":** Distribution authorized to Department of Defense and DOD subcontractors only to protect technical or operational data or information from automatic dissemination under the International Exchange Program or by other means, 10 February 2017. Other requests for this document shall be referred to Agile Combat Support Directorate, Simulators Division (AFLCMC/WNS), Wright-Patterson Air Force Base, Ohio 45433-7249.

**WARNING:** This document contains technical data whose export is restricted by the Arms Export Control Act (Title 22, U.S.C. 2751, et seq.) or the Export Administration Act Of 1979, Title 50, U.S.C., App. 2401, et seq.), as amended. Violation of these export control laws is subject to severe criminal penalties. Disseminate in accordance with provisions of DoD 5230.25.

---

**Table of Contents**

1	Scope .....	1
1.1	Identification .....	1
1.2	System Overview .....	1
1.3	Document Overview .....	1
2	Referenced Documents .....	1
3	Version Description.....	1
3.1	Inventory of Materials Released .....	1
3.2	Inventory of Software Contents .....	2
3.2.1	Aural Cueing System software .....	2
3.2.2	Auto Test Data.....	2
3.2.3	GeoChart Editor.....	2
3.2.4	Host software .....	2
3.2.5	Instructor Operator Station software .....	3
3.3	Changes Installed .....	3
3.4	Adaptation Data .....	3
3.5	Related Documents .....	3
3.6	Installation Instructions.....	3
3.7	Possible Problems and Known Errors.....	3
4	Notes.....	3

---

## 1 Scope

### 1.1 Identification

This document is applicable to software version 4.18N for the Joint Primary Aircraft Training System (JPATS) Ground Based Training System (GBTS) T-6A Flight Training Devices (FTD). Personnel responsible for the Contractor Logistic Support (CLS) of the JPATS GBTS components are the intended recipients of this document.

### 1.2 System Overview

The purpose of the JPATS GBTS is to train pilots in the operation of the T-6A aircraft. The FTD provide the capability to train pilots in a simulated aircraft environment. There are three types of FTD: the Instrument Flight Trainer (IFT), Operational Flight Trainer (OFT), and Unit Training Device (UTD). All three types of FTD have five common computational systems: Host, Instructor Operator Station (IOS), Aural Cueing System (ACS), Flight Deck Input – Output (FDIO), and Electronic Control Loading System (ECLS). The FTD were designed and manufactured by FlightSafety Simulation Systems in Broken Arrow, Oklahoma. Current locations of the JPATS GBTS are Columbus Air Force Base (AFB), Laughlin AFB, Naval Air Station (NAS) Pensacola, Randolph AFB, Sheppard AFB, and Vance AFB.

The JPATS GBTS Training System Support Center (TSSC), located at Randolph AFB in Texas, provides organic configuration management and system modification capabilities in support of the JPATS GBTS. The TSSC provides configuration management for the software described herein.

### 1.3 Document Overview

The purpose of this document is to provide a description of software version 4.18N for the JPATS GBTS FTD produced by the JPATS GBTS TSSC.

## 2 Referenced Documents

MIL-STD-498	Software Development and Documentation 5 December 1994	PDF Version
JPATS GBTS CMP	Configuration Management Plan for the JPATS GBTS 8 August 2000	Revision D

## 3 Version Description

### 3.1 Inventory of Materials Released

The released material consists of a compact disk labeled T-6A FTD SW V4.18N. The applications and data on this CD are intended for installation on the FTD. The configuration item number for the FTD software is 133-021. The instructions for installing this software assume the operating system software is installed.

## **3.2 Inventory of Software Contents**

### **3.2.1 Aural Cueing System software**

update_ACS.bat	10/07/2011
update.exe	08/24/2011
6633amp.cal	04/11/2011
amp.cal	02/10/2010
simcomm_A_tas.ini	08/02/2010
SimSound.exe	05/23/2011
ACS Software Installation.doc	11/21/2011

### **3.2.2 Auto Test Data**

Auto Test Data Installation.doc	06/15/2016
JPATS_ATG_DATA-20160201.zip	02/01/2016

### **3.2.3 GeoChart Editor**

GeoChart Installer.exe	01/14/2016
GeoChartEditorUsersGuide.pdf	01/14/2016
Release Notes.txt	01/12/2016

### **3.2.4 Host software**

HOST Software Installation for Windows 7.doc	07/02/2020
HOST Software Installation for Windows 10.doc	07/02/2020
JPATS_HOST_20200625.zip	06/25/2020

### **3.2.5 Instructor Operator Station software**

IOS Software Installation for Windows 7.doc	07/02/2020
IOS Software Installation for Windows 10.doc	07/02/2020
data1.cab	06/23/2020
data1.hdr	06/23/2020
data2.cab	06/23/2020
engine32.cab	08/05/2002
ikernel.ex_	01/04/2000
layout.bin	06/23/2020
setup.bmp	01/10/2001
setup.boot	06/23/2020
Setup.exe	08/05/2002
Setup.ini	06/23/2020
Setup.inx	06/23/2020

### **3.3 Changes Installed**

- Added BUS TIE switch to the IOS Instrument Repeater page (17-025A)
- Corrected issue with missing localizer Morse code and marker beacon tones (20-006A)
- Performed routine NAVAID updates (20-019A)

### **3.4 Adaptation Data**

This document applies to all non-modernized T-6A FTD without the HOTAS modification (ECP 001).

### **3.5 Related Documents**

Instructor's Positional Handbook for the JPATS GBTS T-6A FTD, Version 4.18N.

### **3.6 Installation Instructions**

Instructions for the installation of the above software are included on the CD. If additional assistance is required, contact the JPATS GBTS TSSC at (210) 652-1251 or DSN 487-1251.

### **3.7 Possible Problems and Known Errors**

Additional details concerning the JPATS FTD software can be found in the Magic Service Desk web application and in the TSSC Prioritized Tasks report.

## **4 Notes**

For further assistance, contact the TSSC Manager at (210) 652-1105 or DSN 487-1105.